Dry Air Engineers

Shop No. 1, Shree Krishna Garden, Excellency, opp. Nagori Dairy,
Midc Road, Mira Road (E) Thane - 401107, Maharashtra
Mob.: 9821825593 / 9321351867
Email : binukr25@gmail.com / dryairengineers@yahoo.com

Authorised Franchisee
GEM EQUIPMENTS (P) Ltd.
GEM
Trust ~ Technology

SERVICE REPORT

Warranty / AMC / PER CALL	Complaint No.
Customer :- Kangaroo Furniture 485, Sharma Estate chinchoti Vasai (E) Ph. No.: Fax No.:	Equipment : AFTer Cooler Model : ACC-010A Sr. No: : 11470-12/22

Nature of Complaint : AFTer Air Cooler is Not work Fan mot

Analysis of Complaint : Fan mote wiring is Not Correct Course of Defect :

Action Token :- checked and observed the fanction of AFTer Cooler the following works has been carried ou.

- Fan moter supply wire connection correct it
- condensor cloned - problem rectified - AFTer done

above fainal has been carried out, Found working g

Spares Used : -	Observations : AFTer Air cooler is Condition is working good. Fan moter work. Good.
	Work Commenced Dt. 20-06-22 Time :
	Work Completed Dt. 20-06-22 Time :
General Instructions Customer : -	Customer Remarks : RAMBHARI
Service Engineer Name : Pankaj Singh	Work attend to our Satisfaction.
Signature : Pankaj Date : 20-6-22	Customers' Name Signature