



# SERVICE REPORT

CUSTOMER NAME & ADDRESS - M/J VARUN MOTORS PVT LTD. NANAK RAMA GUDA, HYD.	SERVICE ENGINEER NAME	NARENDER
	MODEL NO	2KD 004G
CONTACT PERSON - NAME & DESIGNATION - NUMBER M/S. ASHOB - 9949537975	SERIAL NO	8566-10/21
	MANUFACTURER YEAR	2021 (10)
GST-36AABC V2471@12T	ATTENDED DATE	13/04/2022
	COMPLETED DATE	Pending.
COMPLAINT - water coming from	MACHINE TYPE	Ref-Dryal.



### ANALYSIS & WORK DONE -

ATTENDED IN The Above site of  
Checked the all parameters in Air Dryal found the  
Problem was Auto Drain Valve Solinide coil NOT working  
It has to be replace with new one.

- \* Check the controller out put supply found ok.
- \* Check the Solinide coil plug wiring to supply - found ok
- \* Check the Solinide coil magnetizing function found. The  
Problem it's NOT magnetizing & has to be replace with new.

NOTE - there is NO line filter in Air Dryal Air Rule.  
Don't run the Air Dryal with out line filter in Dryal Rule.

### CUSTOMER REMARKS -

SERVICE ENGINEER SIGNATURE & NAME 	CUSTOMER SIGNATURE & SEAL 
--	---



# AIR DRYER TECHNICAL SERVICES

Ph : 9063299452

Address : Shed No. 6/4 to 6/11, Indira Nagar Colony, Boduppal, Hyderabad - 500092.

Email : [Info@airdryertechnicalservices.com](mailto:Info@airdryertechnicalservices.com) • [airdryertechnicalservices@gmail.com](mailto:airdryertechnicalservices@gmail.com) | Website : [www.airdryertechnicalservices.com](http://www.airdryertechnicalservices.com)