

Minutes of Meeting/Action Log

Participants:

Gem Equipments (P) Ltd.:
K.K NAG , Thiruvallur

Mr.M.Balakrishnan
Mr.Surendar

Minutes of Meeting/Action Log

Date: 17.09.18

S.No	Points discussed	Action proposed	Target date	Action By	Completed on	status
1	NOZZLE PIPE UNFORMED MELDED	<p>Product: SCB 200H Supplied on:26.04.2018 Problem: Internal pipes are unformed, melded. Root Cause: High (70 to 85 deg C) inlet water temperature. Conclusion: Fills can withstand upto 85 deg C but internal pipe structure would not withstand. We recommend to change the pipe & pipe fittings material from PVC to C-PVC. This additional cost will bear by customer.</p>		K.K NAG		
2	CENTRE PIPE BROKEN	<p>Product: SCB 200H Supplied on:26.04.2018 Problem: Center pipe broken Root Cause: Possible to mishandling the pipe structure, by mistakenly, any maintenance worker stand on the structure. Found the water flow rate at site is only 20 lps, whereas our recommendation is upto 43 lps. So, there is no change to broken for water flow. Conclusion: There is no issue on our manufacturing methods. Advice to customer to</p>		K.K NAG		

copy issued to: