

**SERVICE REPORT**

**GEM EQUIPMENTS (P) LTD.**

S.F. NO. 103, AVANASHI ROAD, ARASUR, COIMBATORE, TN 641 407, INDIA  
 PHONE : +91 422 2363800 / 836 / 837  
 SERVICE HOT LINE : (O) 93666 31697  
 NORTH - 93601 18523 SOUTH - 93443 31697  
 SPARES : 93456 31697  
 E-mail : service@gemindia.com, parts@gemindia.com  
 Website : www.gemindia.com

Complaint No.:

Equipment : *DESICCANT AIR DRYER*

Model : *HOC 060 A*

SR No. : *5567-6-14*

WARRANTY / AMC / CHARGEABLE

Customer : *CRASIM INDUSTRIES LTD*  
*NACDA - MP*

Ph. No.: *9977444176* Fax No.:

Nature of Complaint : *Most Moisture come in air line*

Analysis of Complaint :


Cause of Defect :

*Air Compressor over capacity compared to Air dryer.*

Action Taken :

*We are visit and check dryer unit so found dryer working satisfactory. so I suggest before dryer one moisture separator and one air tank will be provide for solve your problem. separator and tank eliminate 10-20% moisture from wet air then dryer work effectively.*

Spares Used: ~~After~~ before




Observation :

Work Commenced Date :

Work Completed Date :

General Instructions to Customer :

*After*



Customer Remarks :

Service Engineer Name :

*Sunny*  
*9911941217*

Signature :

Date : *14.12.2019*

Work Attended to our Satisfaction

*Mr. Shwetank Sharma 9977444176*

*Mr. Narendera Sakre*

Customer's Name

Signature *[Signature]* *6262041929*