

SERVICE REPORT

GEM EQUIPMENTS (P) LTD. S.F. NO. 103, AVANASHI ROAD, ARASUR, COIMBATORE, TN 641 407, INDIA PHONE : +91 422 2363800 / 836 / 837 SERVICE HOT LINE : (O) 93666 31697 NORTH - 93601 18523 SOUTH - 93443 31697 SPARES : 93456 31697 E-mail : service@gemindia.com, parts@gemindia.com Website : http://www.gemindia.com		Complaint No.: 10282 Equipment : Air Drier Model : 2KDec 060 SR No. : 4890-06/21	
WARRANTY / AMC / CHARGEABLE			
Customer : Deen Jyoti Hospital, Baramati, MHA			
Ph. No.: 750656507 Fax No.:			
Nature of Complaint : <div style="text-align: center; padding: 10px;"> High Dew Point </div>			
Analysis of Complaint : <div style="text-align: center; padding: 10px;"> - </div>		Cause of Defect : <div style="text-align: center; padding: 10px;"> - </div>	
Action Taken : <div style="text-align: center; padding: 10px;"> Leak was found at sensor and not and then removed it and vacuumized and checked to 4. Pressure </div>			
Spares Used :		Observation : <div style="border: 1px solid black; padding: 5px; margin-top: 5px;"> Work Commenced Date : 23/06/22 Work Completed Date : 23/06/22 </div>	
General Instructions to Customer :		Customer Remarks : <div style="text-align: center; padding: 10px;"> SUNIL PAWAR Professor & Head Department of Anesthesia Govt. Medical College & General Hospital Baramati, Dist. Pune </div>	
Service Engineer Name : J. Abdul Rehman 8508159944 <div style="text-align: center; padding: 10px;"> Signature: </div>		Work Attended to our Satisfaction <div style="text-align: center; padding: 10px;"> Signature: </div>	
Date : 23/06/22		Customer's Name	