



Airmatic Gem

SERVICE REPORT

FREE / CHARGEABLE

247, Raja Ram Mohan Roy Road,
Kokata - 700 008
Mobile No. : 093322 39000, ~~093322 89900~~ ⁸¹⁰⁰¹¹¹⁹⁰⁰
Email Id : airmaticgem@gmail.com

Complaint No : 4328
Equipment : Air Dryer
Model : 2kg7-100
S. No. : 5385-06-18

Name of Customer & Address :
MIS Keventor Agro Itk
Subas Nagar - C Bansa
Kolkata

Ph. No. : Fax No. :

Nature of Complaints :

Dryer is not working

Cause of Defect :

I will visit site on 28th Dec and check the unit. Dryer hot gas valve pipe is broken and electrical box also damaged.

Details of Repairs Made :

Spares Used :

this is for transit damage

General Instructions to Customer :

Spares received
Hot Gas Valve - 100
R 134a Gas -
Com - Oil

Service Engineer :

Name : M. Mahua

Signature :

Date : 28.12.18

Work Commenced Date : 28.12.18

Work Completed Date : 28.12.18

Customer Remarks :

Work Attended to our Satisfaction

This problem solve as soon as possible

R. N. Mahua
Keventor Agro Ltd.
Customer Name

R. N. Mahua
Signature