

SERVICE REPORT

GEM EQUIPMENTS (P) LTD.

S.F. NO. 103, AVANASHI ROAD, ARASUR, COIMBATORE, TN 641 407, INDIA
 PHONE : +91-422-2363800 / 836 / 837
 SERVICE HOT LINE : (0) 93666 31697
 NORTH - 93601 18523 SOUTH - 93443 31697
 SPARES : 93456 31697
 E-mail : service@gemindia.com, parts@gemindia.com
 Website : www.gemindia.com

Complaint No.: 4470
 Equipment : Ref Air Dryer
 Model : 910075
 SR No. : 7776-09/12

WARRANTY / AMC / CHARGEABLE

Customer : Park Agency (P) Ltd.
 Khanda, Onice.

Ph. No.: 9999993353 Fax No.:

Nature of Complaint :

High Dew Point. LPT up

Analysis of Complaint :

Cause of Defect :

Gas Leakage.

Action Taken :

Check the dryer and found there was gas leakage from Condenser Inlet pipe. So arrested then Heliofill₂ with 950PSI. After confirm there was no leakage in the dryer. Then vacuum & amt checked 40°C gas leak. Now dryer running with satisfactory Dew point 2-5°C and drain valve also working fine.

Spares Used :

- ① V-107C gas - 4kg.
- ② Gas filling rods.

Observation :

Work Commenced Date : 31/8/19

Work Completed Date : 1/9/19

General Instructions to Customer :

- ① Clean Condenser Daily.
- ② Check & Clean Drain Valve Monthly.
- ③ Check Dew Point Daily.

Customer Remarks :

The dryer is working under observation.

Service Engineer Name :

J. Rajase

Work Attended to our Satisfaction

[Signature]
01/02/19

Signature :

Date : 1/9/19

Customer's Name

Signature